



Technical Service Bulletin

Technical Service Bulletin: tsb101886

Released Date: 19-Apr-2006

Update to Procedure 001-054 (Piston and Connecting Rod Assembly), Addition of Missing Procedure Steps

Update to Procedure 001-054 (Piston and Connecting Rod Assembly), Addition of Missing Procedure Steps

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to update procedure 001-054 with the missing Disassemble, Clean and Inspect for Reuse, Assemble, and Install steps.

Note : This is a product improvement and is **not** subject to campaign.

Note : This change will **not** release any new parts or affect any part numbers.

Related Procedures

09-001-054
(/qs3/pubsys2/xml/en/procedures/09/09-001-054.html)

Piston and Connecting Rod Assembly
(/qs3/pubsys2/xml/en/procedures/09/09-001-054.html)

Last Modified: 19-Apr-2006