



Technical Service Bulletin

Technical Service Bulletin: tsb101929	Released Date: 09-Apr-2007
Symptom Tree Revision, Oil Pressure High	

Symptom Tree Revision, Oil Pressure High

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Symptom Tree, 3666003-t104, Lubricating Oil Pressure High, to update a procedure reference for correction, when the pressure regulator valve is stuck open.

Lubricating Oil Pressure High

Last Modified: 09-Apr-2007
