



Technical Service Bulletin

Technical Service Bulletin: tsb101963

Released Date: 31-Aug-2006

Reference Amendment in Procedure 005-999

Reference Amendment in Procedure 005-999

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to amend a reference in Procedure 005-999 in the C-Series Troubleshooting and Repair Manual. The change is the reference to Procedure 006-003 (Air in Fuel) for bleeding air from the fuel system, in place of Procedure 006-001 (AFC Air Tube).

Related Procedures

41-005-999

(/qs3/pubsys2/xml/en/procedures/41/41-005-999.html)

Fuel System - Overview

(/qs3/pubsys2/xml/en/procedures/41/41-005-999.html)

Last Modified: 31-Aug-2006