



Technical Service Bulletin

Technical Service Bulletin: tsb101986

Released Date: 26-Oct-2006

Revision to Cooling Fan Drive Belt

Revision to Cooling Fan Drive Belt

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a caution applying to the removal of the cooling fan belt for all C and L series engines equipped with an automatic belt tensioner. The caution warns against the use of a socket extension when removing and installing the cooling fan belt. The improper use of a socket extension can cause the automatic belt tensioner arm to break.

Related Procedures

100-008-002
(/qs3/pubsys2/xml/en/procedures/100/100-008-002.html)

Drive Belt, Cooling Fan
(/qs3/pubsys2/xml/en/procedures/100/100-008-002.html)

Last Modified: 26-Oct-2006