



Technical Service Bulletin

Technical Service Bulletin: tsb102020	Released Date: 24-Oct-2006
Revision to Symptom Tree, Lubricating Oil Pressure Low	

Revision to Symptom Tree, Lubricating Oil Pressure Low

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Symptom Tree 3666003-t105 for C and C8.3 Series engines. Unnecessary steps are removed and a reference bulletin is changed in 'Correction' step 4.
--

NAME b-105.t

Last Modified: 24-Oct-2006
