



Technical Service Bulletin

Technical Service Bulletin: tsb102025

Released Date: 23-Oct-2006

Graphics Revision to Lubricating Oil Pressure Regulator (Main Rifle) Procedure

Graphics Revision to Lubricating Oil Pressure Regulator (Main Rifle) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises and updates graphics in Lubricating Oil Pressure Regulator (Main Rifle) Procedure 007-029, for 6C, C8.3, ISC, and QSC8.3 engines.

Related Procedures

100-007-029
(/qs3/pubsys2/xml/en/procedures/100/100-007-029.html)

Lubricating Oil Pressure Regulator (Main Rifle)
(/qs3/pubsys2/xml/en/procedures/100/100-007-029.html)

Last Modified: 23-Oct-2006