



Technical Service Bulletin

Technical Service Bulletin: tsb102083

Released Date: 21-Mar-2007

Revision to Install Step of Lubricating Oil Filter (Spin-On) Procedure

Revision to Install Step of Lubricating Oil Filter (Spin-On) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the amount of turn when installing the lubricating oil filter, in Procedure 007-013, Lubricating Oil Filter (Spin-On).

Related Procedures

100-007-013
(/qs3/pubsys2/xml/en/procedures/100/100-007-013.html)

Lubricating Oil Filter (Spin-On)
(/qs3/pubsys2/xml/en/procedures/100/100-007-013.html)

Last Modified: 21-Mar-2007