



# Technical Service Bulletin

Technical Service Bulletin: tsb102149

Released Date: 23-Feb-2007

Revision, Install Step, Cylinder Head Procedure

## Revision, Install Step, Cylinder Head Procedure

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic announces a correction to the torque requirements in the install step of Procedure 002-004 (Cylinder Head).

### Related Procedures

45-002-004-tr  
(/qs3/pubsys2/xml/en/procedures/45/45-002-004-tr.html)

Cylinder Head  
(/qs3/pubsys2/xml/en/procedures/45/45-002-004-tr.html)

Last Modified: 23-Feb-2007