



Technical Service Bulletin

Technical Service Bulletin: tsb102273

Released Date: 05-Sep-2007

Revision, Install Step, (Crankshaft Seal, Front) Procedure

Revision, Install Step, (Crankshaft Seal, Front) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the part number for the crankshaft seal installer in the Install step of Procedure 001-023 (Crankshaft Seal, Front) in Section 1.

Related Procedures

100-001-023-tr
(/qs3/pubsys2/xml/en/procedures/100/100-001-023-tr.html)

Crankshaft Seal, Front
(/qs3/pubsys2/xml/en/procedures/100/100-001-023-tr.html)

Last Modified: 05-Sep-2007