



Technical Service Bulletin

Technical Service Bulletin: tsb102441	Released Date: 31-Aug-2007
Revision, Symptom Tree t105, Lubricating Oil Pressure Low	

Revision, Symptom Tree t105, Lubricating Oil Pressure Low

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises symptom tree T105 (Lubricating Oil Pressure Low) to include additional steps for the instant loss of lubricating engine oil. The additional steps provide a list of components that **must** be checked when this condition occurs.

Lubricating Oil Pressure Low

Last Modified: 31-Aug-2007
