



Technical Service Bulletin

Technical Service Bulletin: tsb102471

Released Date: 04-Sep-2007

Replacement, Intake Manifold Pressure Procedure, C Series Troubleshooting and Repair Manual

Replacement, Intake Manifold Pressure Procedure, C Series Troubleshooting and Repair Manual

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic replaces Procedure 010-057 (Intake Manifold Pressure) in the Troubleshooting and Repair Manual, C Series Engines, Bulletin 3666003.

Related Procedures

41-010-057
(/qs3/pubsys2/xml/en/procedures/41/41-010-057.html)

Intake Manifold Pressure
(/qs3/pubsys2/xml/en/procedures/41/41-010-057.html)

Last Modified: 04-Sep-2007