



Technical Service Bulletin

Technical Service Bulletin: tsb102515

Released Date: 30-Oct-2007

Revision, Multiple Steps, Timing Pin Housing and Gear Housing (Front)

Revision, Multiple Steps, Timing Pin Housing and Gear Housing (Front)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic releases Procedure 001-049 (Timing Pin Housing) and revises Procedure 001-033 (Gear Housing, Front) to include a reference to Procedure 001-049 (Timing Pin Housing).

Related Procedures

41-001-033 (/qs3/pubsys2/xml/en/procedures/41/41-001-033.html)	Gear Housing, Front (/qs3/pubsys2/xml/en/procedures/41/41-001-033.html)
41-001-049 (/qs3/pubsys2/xml/en/procedures/41/41-001-049.html)	Timing Pin Housing (/qs3/pubsys2/xml/en/procedures/41/41-001-049.html)

Last Modified: 30-Oct-2007