



Technical Service Bulletin

Technical Service Bulletin: tsb102561

Released Date: 13-Dec-2007

Revision, Inspect for Reuse Step, Camshaft Procedure

Revision, Inspect for Reuse Step, Camshaft Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises a note in the Clean and Inspect step in Procedure 001-008 (Camshaft). The note identifies additional components to replace if a new camshaft is installed.

Related Procedures

41-001-008
(/qs3/pubsys2/xml/en/procedures/41/41-001-008.html)

Camshaft
(/qs3/pubsys2/xml/en/procedures/41/41-001-008.html)

Last Modified: 13-Dec-2007