



Technical Service Bulletin

Technical Service Bulletin: tsb102869

Released Date: 13-May-2008

Injector Protrusion Procedure Revision

Injector Protrusion Procedure Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the conversion in Procedure 002-022 (Injector Protrusion).

Related Procedures

41-002-022
(/qs3/pubsys2/xml/en/procedures/41/41-002-022.html)

Injector Protrusion
(/qs3/pubsys2/xml/en/procedures/41/41-002-022.html)

Last Modified: 13-May-2008