



Technical Service Bulletin

Technical Service Bulletin: tsb102944

Released Date: 24-Jul-2008

Cooling System Procedure, Fill Section Revisions

Cooling System Procedure, Fill Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 008-018 (Cooling System) in Section 8 of the Troubleshooting and Repair Manual, C Series Engines, Bulletin 3666003 and Troubleshooting and Repair Manual, C8.3G, C Gas Plus, and L Gas Plus Engines, Bulletin 3666206. A caution and information related to the operation of the cab heater were added to the Fill section.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

100-008-018-tr
(/qs3/pubsys2/xml/en/procedures/100/100-008-018-tr.html)

Cooling System
(/qs3/pubsys2/xml/en/procedures/100/100-008-018-tr.html)

Last Modified: 24-Jul-2008