



Technical Service Bulletin

Technical Service Bulletin: tsb103000

Released Date: 28-Aug-2008

Camshaft Bushings Procedure, Remove Section Revision

Camshaft Bushings Procedure, Remove Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Remove Section of Procedure 001-010 (Camshaft Bushings) in Section 1 of the C Series Troubleshooting and Repair Manual, Bulletin 3666003. The bushing installation and remove tool part number has changed and the Hydraulic Actuator Kit has been added along with the Camshaft Bushing Installation/Removal Kit.

Related Procedures

41-001-010
(/qs3/pubsys2/xml/en/procedures/41/41-001-010.html)

Camshaft Bushings
(/qs3/pubsys2/xml/en/procedures/41/41-001-010.html)

Last Modified: 28-Aug-2008