



Technical Service Bulletin

Technical Service Bulletin: tsb103001

Released Date: 28-Aug-2008

Service Tools Procedure Additions

Service Tools Procedure Additions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds two kits to the cylinder block service tool list. They are (1) Hydraulic Actuator Kit, Part Number 3823621, and (2) Camshaft Bushing Installation and Removal Kit, Part Number 3162253, to Procedure 022-001 (Service Tools) in Section 1 of the C Series Troubleshooting and Repair Manual, Bulletin 3666003.

Related Procedures

41-022-001_01
(/qs3/pubsys2/xml/en/procedures/41/41-022-001_01.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/41/41-022-001_01.html)

Last Modified: 28-Aug-2008