



Technical Service Bulletin

Technical Service Bulletin: tsb103091

Released Date: 17-Sep-2008

(Valve Guide, Cylinder Head) Procedure, Inspect for Reuse Section Revision

(Valve Guide, Cylinder Head) Procedure, Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Inspect for Reuse section of Procedure 002-017 (Valve Guide, Cylinder Head) in Section 2 of the C Series Engines Troubleshooting and Repair Manual, Bulletin 3666003.

Related Procedures

41-002-017
(/qs3/pubsys2/xml/en/procedures/41/41-002-017.html)

Valve Guide, Cylinder Head
(/qs3/pubsys2/xml/en/procedures/41/41-002-017.html)

Last Modified: 17-Sep-2008