



Technical Service Bulletin

Technical Service Bulletin: tsb103223

Released Date: 20-Nov-2008

Maintenance Schedule Addition

Maintenance Schedule Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 102-002 (Maintenance Schedule) to include a recommended injector replacement at engine half life to rebuild.

Related Procedures

20-102-002-om
(/qs3/pubsys2/xml/en/procedures/20/20-102-002-om.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/20/20-102-002-om.html)

Last Modified: 20-Nov-2008