



Technical Service Bulletin

Technical Service Bulletin: tsb103224

Released Date: 20-Nov-2008

Procedure 006-026 (Injector), Replace Section Revision

Procedure 006-026 (Injector), Replace Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 006-026 (Injector) in Section 9 of the Operation and Maintenance Manual QSK19 and QSK19 CM850 Modular Common Rail System, Bulletin 3666120. This procedure recommends injector replacement at engine half life to rebuild.

Related Procedures

20-006-026-om
(/qs3/pubsys2/xml/en/procedures/20/20-006-026-om.html)

Injector
(/qs3/pubsys2/xml/en/procedures/20/20-006-026-om.html)

Last Modified: 20-Nov-2008