



Technical Service Bulletin

Technical Service Bulletin: tsb103335

Released Date: 13-Feb-2009

Lubricating Oil Leaks Procedure, Initial Check Section Revision

Lubricating Oil Leaks Procedure, Initial Check Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 007-024 in Section 7 of the C Series Engines Troubleshooting and Repair Manual, Bulletin 3666003. A black light kit has been added to aid in troubleshooting external oil leaks.

Related Procedures

41-007-024
(/qs3/pubsys2/xml/en/procedures/41/41-007-024.html)

Lubricating Oil Leaks
(/qs3/pubsys2/xml/en/procedures/41/41-007-024.html)

Last Modified: 13-Feb-2009