



Technical Service Bulletin

Technical Service Bulletin: tsb103509

Released Date: 19-May-2009

Lubricating Oil Leaks Procedure, Initial Check Section Revision

Lubricating Oil Leaks Procedure, Initial Check Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Initial Check section in Procedure 007-024 (Lubricating Oil Leaks). The engine is to be operated under load, if necessary, to duplicate the leak conditions.

Related Procedures

41-007-024
(/qs3/pubsys2/xml/en/procedures/41/41-007-024.html)

Lubricating Oil Leaks
(/qs3/pubsys2/xml/en/procedures/41/41-007-024.html)

Last Modified: 19-May-2009