



Technical Service Bulletin

Technical Service Bulletin: tsb103897

Released Date: 21-Aug-2009

Camshaft Procedure, Measure Section Revision

Camshaft Procedure, Measure Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-008 (Camshaft) to provide updated camshaft wear limit specifications and improve the readability of the specification tables.

Related Procedures

41-001-008
(/qs3/pubsys2/xml/en/procedures/41/41-001-008.html)

Camshaft
(/qs3/pubsys2/xml/en/procedures/41/41-001-008.html)

Last Modified: 21-Aug-2009