



Technical Service Bulletin

Technical Service Bulletin: tsb104010

Released Date: 03-Dec-2009

Piston and Connecting Rod Assembly Procedure, Assemble Section Revision

Piston and Connecting Rod Assembly Procedure, Assemble Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the orientation of the four digit number stamped on the connecting rod and cap in the Assemble section of Procedure 001-054 (Piston and Connecting Rod Assembly).

Related Procedures

41-001-054
(/qs3/pubsys2/xml/en/procedures/41/41-001-054.html)

Piston and Connecting Rod Assembly
(/qs3/pubsys2/xml/en/procedures/41/41-001-054.html)

Last Modified: 03-Dec-2009