



Technical Service Bulletin

Technical Service Bulletin: tsb104050

Released Date: 17-Feb-2010

Cylinder Head Procedure, Multiple Section Revisions

Cylinder Head Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 002-004 (Cylinder Head) for the QSK19 Service Manual. The revisions include the following:

- Cylinder head thickness specification
- Resurfacing guidelines
- Injector protrusion specification.

Related Procedures

20-002-004-tr
(/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/20/20-002-004-tr.html)

Last Modified: 17-Feb-2010