



Technical Service Bulletin

Technical Service Bulletin: tsb104208

Released Date: 18-May-2010

Piston Rings Procedure, Multiple Section Revisions

Piston Rings Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Part Topic revises Procedure 001-047 (Piston Rings) in the K19 Service Manual, Bulletin 4021499 and the QSK19, QSK19 CM850 MCRS, and QSK19 CM2150 MCRS Service Manual, Bulletin 4011592. The piston ring gap specifications for new piston rings have been added and additional specifications have been added to aid in the exact placement of the piston ring for installation.

Related Procedures

18-001-047 (/qs3/pubsys2/xml/en/procedures/18/18-001-047.html)	Piston Rings (4021499) (/qs3/pubsys2/xml/en/procedures/18/18-001-047.html)
20-001-047 (/qs3/pubsys2/xml/en/procedures/20/20-001-047.html)	Piston Rings (4021592) (/qs3/pubsys2/xml/en/procedures/20/20-001-047.html)

Last Modified: 18-May-2010