



Technical Service Bulletin

Technical Service Bulletin: tsb104241

Released Date: 06-Jul-2010

(Bearings, Connecting Rod) Procedure, Clean and Inspect for Reuse Section Revision

(Bearings, Connecting Rod) Procedure, Clean and Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-005 (Bearings, Connecting Rod) in the QSK19, QSK19 CM850 MCRS, and QSK19 CM2150 MCRS Service Manual, Bulletin 4021592. The revision adds reuse guidelines for the connecting rod bearings to the Clean and Inspect for Reuse section of this procedure.

Related Procedures

20-001-005
(/qs3/pubsys2/xml/en/procedures/20/20-001-005.html)

Bearings, Connecting Rod
(/qs3/pubsys2/xml/en/procedures/20/20-001-005.html)

Last Modified: 06-Jul-2010