



Technical Service Bulletin

Technical Service Bulletin: TSB130183	Released Date: 09-Jan-2014
Diesel Exhaust Fluid Doser Pump Override Test Enumeration 13	

Diesel Exhaust Fluid Doser Pump Override Test Enumeration 13

Core Issue

When running this test, INSITE™ electronic service tool could display the following:

"The test status parameter has a value outside of the expected range. The value of the test status parameter is equal to 13."


This will be displayed while the system is dosing. The test will automatically continue after dosing has completed. The issue is due to the fact that the engine control module (ECM) software supported this enumeration before it was requested in INSITE™ electronic service tool.

Confirmation

N/A

Resolution

This message will be updated to "Please wait while the system is dosing." with the release of INSITE™ 8.0.1



19r00194

INSITE™ electronic service tool display

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2013-12-30	Module Created

Last Modified: 09-Jan-2014
