



Technical Service Bulletin

Technical Service Bulletin: TSB140054

Released Date: 19-Feb-2015

New Piston Pin for QSK19 Engines

New Piston Pin for QSK19 Engines

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Contents

This document introduces a new piston pin and associated piston kits.

Product Affected

- QSK19 CM500
- QSK19 CM850 MCRS
- QSK19 CM2150 MCRS

Description of Change

The new piston pin has a straight inner diameter. See Figure 1.

The old piston pin has a scalloped inner diameter. See Figure 2.

Reason for Change

The new piston pin is more robust and can withstand greater cylinder stresses.

Service Instructions

The new style piston pin or corresponding piston kit are recommended if replacement is required.

The existing style piston pin and new style piston pin **must not** be mixed in the same engine.

Service Parts Availability

Service parts are available. See Table 1, Table 2 for part numbers.

Table 1, QSK19 Piston Pins		
Description	Existing Part Number	New Part Number
Piston Pin	4916767	4910289

Table 2, QSK19 Piston Kits

Description	Existing Kit Part Number	New Kit Part Number
Kit, Piston	4090029	4352366
Kit, Piston	4352138	4352367
Kit, Engine Piston	4955233	4352368
Kit, Engine Piston	4955234	4352369
Kit, Engine Piston	4955235	4352370
Kit, Engine Piston	4955236	4352371

Part Disposition

None

Production Status

Implemented for production. See Table 3.

Table 3, Plant Information

New Part Number	ESN First	Build Date	Plant
4910289	Not Available	20 February 2014	Seymour Engine Plant

Engine build date can be found on the engine dataplate.

Publications Affected

None



Figure 1, New Piston Pin



Figure 2, Existing Piston Pin

Document History

Date	Details
2014-4-30	Module Created
2015-2-9	General format changes and added piston kit table (3) that includes existing and new piston pins.

Last Modified: 19-Feb-2015
