



Technical Service Bulletin: TSB160051

Released Date: 16-May-2016

New Stainless Steel Coolant Shut-Off Valve

New Stainless Steel Coolant Shut-Off Valve

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document was originally published as Service Parts Topic 97T8-12.

Product Affected

- 6C (All Versions)
- C8.3 (All Version)
- ISC (All Versions)

Description of Change

Beginning in March 1997, silicon grease was applied to the plastic shut-off valve, Part Number 3912837, in production **only**. This document announces a new stainless steel coolant shut-off valve, Part Number 3010536, available for service.

Reason for Change

Cooling system corrosion by-products and debris can settle between the coolant shut-off valve and bore, causing binding. If excessive force is applied to a binding coolant shut-off valve, the coolant shut-off valve can break off in the coolant thermostat housing.

Service Instruction

If a coolant shut-off valve malfunction occurs in the field, replace plastic coolant shut-off valve, Part Number 3912837, with new stainless steel shut-off valve, Part Number 3010536. The new stainless steel shut-off valve, Part Number 3010536, is the **only** coolant shut-off valve available for service.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsoleted	Superseded	New Part Number
Coolant Shut-Off Valve	3912837	Yes	Yes	3010536

Document History

Date	Details
2016-5-16	Module Created

Last Modified: 16-May-2016