



Technical Service Bulletin

Technical Service Bulletin: TSB170013

Released Date: 31-Jan-2017

New Rear Crankshaft Seal with Dust Lip

New Rear Crankshaft Seal with Dust Lip

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

This TSB **only** applies to the following engines produced in India:

- NH/NT (All Versions)
- NTA14 (All Versions)
- QSN14 (All Versions)

Description of Change

This document announces a new rear crankshaft seal with dust lip which replaces the single lip rear crankshaft seal.

Reason for Change

New rear crankshaft seal has dust lip seal to prevent dirt ingress.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Seal, Oil	211253	Yes	Yes	4346552

Note : Rear crankshaft seal, dual lip, Part Number 3001772, used on N14, NH/NT 855 Rail and Mining market has **not** changed. Rear crankshaft seal and related service rear crankshaft seal part numbers will remain unchanged.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information			
Model	ESN First	Build Date*	Plant**
NH/NT 855	25422680	22-November-16	CIL/India
NTA14	25422805	6-December-16	CIL/India
QSN14 CM876	25423316	20-December-16	CIL/India
*Engine build date can be found on the engine data plate.			
**Engine manufacturing plant can be found on the engine data plate.			

Document History

Date	Details
2017-1-20	Module Created