



Technical Service Bulletin

Technical Service Bulletin: TSB190013

Released Date: 17-Jan-2019

New Cam Follower Covers

New Cam Follower Covers

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK19, All configurations

Description of Change

New camshaft follower covers were designed to fit new edge molded rubber gaskets.

Reason for Change

New camshaft follower covers were introduced as gasket was commonized.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Cover, Camshaft Follower	3329530	Yes	Yes	5483698
Cover, Camshaft Follower	3090178	Yes	Yes	4328024
Cover, Camshaft Follower	3480213	Yes	Yes	5483672
Cover, Camshaft Follower	NA	No	No	4314206

Part Compatibility

New camshaft follower cover is **only** compatible with the use of camshaft follower cover gasket Part Number 4314215.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

Camshaft Cover Part Number	ESN First	Build Date¹	Plant
5483698	37277065	19 Oct 2018	Seymour Engine Plant
4328024	37276697	18 Oct 2018	Seymour Engine Plant
5483672	37277471	7 Jan 2019	Seymour Engine Plant
4314206	37277137	27 Nov 2018	Seymour Engine Plant
¹ Engine build date can be found on the engine dataplate.			

Document History

Date	Details
2019-1-15	Module Created

Last Modified: 17-Jan-2019
