



Technical Service Bulletin

Technical Service Bulletin: TSB240145

Released Date: 15-Jul-2024

Improved Coolant Bypass Tube P Clip on Construction BH60 Dump Truck

Improved Coolant Bypass Tube P Clip on Construction BH60 Dump Truck

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK19 CM2150 MCRS
- Shop Order Number SO63039, A061H855
- Construction BH60 Dump

Description of Change

- An improved coolant bypass tube P clip is available.
- The new coolant bypass P Clip is thicker.

Reason for Change

The existing coolant bypass tube P clip is incapable of withstanding the coolant tube load and vibration. A broken coolant bypass tube P Clip can lead to increased noise from the engine.

Resolution

If coolant bypass tube P clip has malfunctioned, replace existing P clip part number with new P clip part number.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
P Clip	3090165	No	Yes	3282250

Part Inventory Action

Use existing part number inventory before using the new part number.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

Product	ESN First	Build Date ¹	Plant
QSK19C	25489829	24 November 2023	CIL -Kothrud Engine plant

¹Generator Set/Engine build date can be found on the Generator Set/engine data plate.

Document History

Date	Details
2024-7-9	Module Created

Last Modified: 15-Jul-2024