



Technical Service Bulletin: TSB190119

Released Date: 26-Jul-2019

Introduction of New Alternator Pulley in QSK50 Engine

Introduction of New Alternator Pulley in QSK50 Engine

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK50 CM2150 MCRS (**Industrial Only**)

Description of Change

This document announces an introduction of new alternator pulley in QSK50 CM2150 MCRS engine model.

Reason for Change

It was observed that the pulley was press fitted on the shaft and affected the key movement, which caused charging alternator failure.

Service Parts Availability

It was observed that the pulley was press fitted on the shaft and affected the key movement, which caused charging alternator failure.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Alternator Pulley Part Numbers

Part Description	Existing Part Number	New Part Number
Pulley, Alternator	3014711	4399016

Part Compatibility

This part cannot be mixed within the same engine because of modification done and this part is compatible as per Table 1 **only**.

Part Structure

The old part number should be replaced with the new part number.

Part Inventory Action

The old part numbers in stock should **not** be used.

Production Status

Implemented for production. See Table 2.

Table 2, Production Information		
Engine Seriel Number (ESN) First	Build Date*	Plant
25443943	22 February, 2019	KCL, Cummins India LTD.
*Engine build date can be found on the engine dataplate.		

Document History

Date	Details
2019-7-3	Module Created
2019-7-17	Corrected outfile
2019-7-26	Corrected product affected