



Technical Service Bulletin

Technical Service Bulletin: tsb100185	Released Date: 03-Dec-2002
Low Temperature Aftercooled (LTA) Water Pump Rebuild Kit	

Low Temperature Aftercooled (LTA) Water Pump Rebuild Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces pump service kit, Part Number 4085922, for rebuilding low temperature aftercooled water pumps, Part Number 4085944, for the QSK45 and QSK60 series engines.

Last Modified: 03-Dec-2002
