



Technical Service Bulletin

Technical Service Bulletin: tsb100219

Released Date: 21-Jul-2003

Hand Hole Cover o-ring Change

Hand Hole Cover o-ring Change


Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin provides information regarding the product improvement of the o-ring for the hand hole cover on QSK45 and QSK60 engines. This improvement consists of an o-ring material change.

The purpose of this change is to improve o-ring durability.



The original o-ring, Part Number 3089370, was made from a nitrile based material. The new o-ring, Part Number 4100660, is made from a viton based material. Engine serial number first for this change 33153345, build date January 21, 2003

This part is **not** subject to a campaign or TRP.

