



Technical Service Bulletin

Technical Service Bulletin: tsb100226	Released Date: 03-Aug-2009
Phase 2.0 Harness Introduction	

Phase 2.0 Harness Introduction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin has been superseded by 09T19-144. Please replace this topic with 09T19-144.

Last Modified: 03-Aug-2009
