



Technical Service Bulletin

Technical Service Bulletin: tsb100228	Released Date: 08-Sep-2003
Cummins branded Prestolite Alternator	

Cummins branded Prestolite Alternator

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service Parts Topic is to introduce the new brushless Cummins Branded Prestolite alternator on QSK45 and QSK60 industrial engines. The new brushless alternator was introduced to improve reliability in high vibration and dusty environments found in industrial applications. Cummins Branded Delco 31SI alternator part number 4016557 has been obsoleted and superceded by the Cummins Branded Prestolite part number 4100763.

When installing part number 4100763 in place of part number 4016557 mounting flange part number 3094584 must also be installed.

ESN first was 33152994 built October 21, 2002.

Note : This is a product improvement not subject to campaign.

Last Modified: 08-Sep-2003
