



Technical Service Bulletin

Technical Service Bulletin: tsb100435

Released Date: 25-Feb-2008

Fuel Rail Manifold Gasket

Fuel Rail Manifold Gasket

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin supersedes topic 06T6-4; replace 06T6-4 with this topic.

This Technical Service Bulletin introduces the new fuel rail manifold gaskets for use on the QSK 45/60 engines.

The new gasket (nickel plated), Part Number 3637870, replaces the present gasket, Part Number 4086222. Please scrap any of the old gaskets, Part Number 4086222, that remain in distributor stock.

The new gaskets are nickel plated. This will reduce the possibility of any fretting issues seen with the old gasket on the one piece fuel manifold.

Torque for the fuel manifold mounting capscrews is unchanged.

The effective date for the new gasket is 29th November 2005.

Engine	First ESN
QSK45	33162393
QSK60	33162378

Note : This is a product improvement and not subject to campaign or TRP.

Last Modified: 25-Feb-2008