



Technical Service Bulletin

Technical Service Bulletin: tsb100800

Released Date: 10-Dec-2010

New Connecting Rod Bearing

New Connecting Rod Bearing

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Note : The information in this document has been superseded. For the connecting rod bearing information, refer to TSB101100. This document will be kept active for information purposes only.

This document announces the release of a new angle split connecting rod bearing for the QSK45 and QSK60 engines. The new connecting rod bearing contains a new VP2i B-E material.

The VP2i B-E material angle split connecting rod bearing supersedes the VP2q B-E material angle split connecting rod bearing.

Since production changed to a different connecting rod design, this new bearing will be used for service **only**. Therefore, no engine serial number (ESN) first is being provided.

Table 1 identifies the part numbers for the old and new connecting rod bearings.

Table 1, Connecting Rod Bearings

Type	Old Part Number	New Part Number
Connecting Rod Bearing	3636495	3639827

Note : This is a product improvement and is not subject to campaign or TRP.

Document History

Date	Details
2010-11-23	Revision

Last Modified: 10-Dec-2010

