



Technical Service Bulletin

Technical Service Bulletin: tsb101159	Released Date: 15-May-2002
Fan Hub Rebuild Procedure	

Fan Hub Rebuild Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic introduces the new procedure for rebuilding the fan hub, belt driven, on QSK45 and QSK60 engines.

Note : This is a product improvement and is not subject to campaign.

Last Modified: 15-May-2002
