



Technical Service Bulletin

Technical Service Bulletin: tsb101164

Released Date: 31-May-2002

Main Bearing Bore Alignment

Main Bearing Bore Alignment

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic describes the procedure to check the main bearing bore alignment of the QSK45 and QSK60 series engines. This procedure will be included in the future QSK45 and QSK60 Shop manual, Bulletin 4021373.

Table 1, Service Tools for the QSK45 and QSK60 Main Bearing Bore Alignment

Part Description	Part Number
Centering Ring	3164873
Checking Ring	3164872
Checking Bar	3375061

Last Modified: 31-May-2002