



Technical Service Bulletin

Technical Service Bulletin: tsb101165	Released Date: 17-Jun-2002
Main Bearing Cap Side Capscrew Torque	

Main Bearing Cap Side Capscrew Torque

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is to revise the stated torque value in the QSK45/60 Troubleshooting and Repair manual, bulletin number, 3666261 (</qs3/portal/manualviewer.html?path=/qs3/pubsys2/xml/en/outlines/3666261.html>).

On page 1-24, the manual states the main bearing cap side capscrew torque value as 390 N•m [288 ft-lb].

The correct torque value is 304 N•m [225 ft-lb].

Please alter your manuals to reflect this change.

Last Modified: 17-Jun-2002
