



Technical Service Bulletin

Technical Service Bulletin: tsb101184

Released Date: 11-Apr-2007

Revision to Low Temperature Aftercooler (LTA) Water Pump Procedure

Revision to Low Temperature Aftercooler (LTA) Water Pump Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the Low Temperature Aftercooler (LTA) Water Pump, Procedure 008-109 (/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html), in the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Related Procedures

56-008-109-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html)

Low-Temperature Aftercooler (LTA) Water Pump
(/qs3/pubsys2/xml/en/procedures/56/56-008-109-tr.html)

Last Modified: 11-Apr-2007