



Technical Service Bulletin

Technical Service Bulletin: tsb101241	Released Date: 22-Mar-2004
Revision to T082-15, T082-25, and T096	

Revision to T082-15, T082-25, and T096

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces the following troubleshooting trees for QSK45 and QSK60 series engines: T082-15, Exhaust Temperature is High (Multiple Cylinders), T082-25, Exhaust Temperature is High (Single Cylinders), and T096, Intake Manifold Air Temperature Above Specification.

Exhaust Temperature is High (Multiple Cylinders) Exhaust Temperature is High (Single Cylinder) Intake Manifold Air Temperature Above Specification

Last Modified: 22-Mar-2004
