



Technical Service Bulletin

Technical Service Bulletin: tsb101331

Released Date: 17-Nov-2003

Using Heat Indicator Markers to Check Exhaust Port Temperature.

Using Heat Indicator Markers to Check Exhaust Port Temperature.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is adding a service tool and creating procedures for using heat indicator markers to locate cold or misfiring engine cylinders.

Note : This is a product improvement and not subject to campaign.

Related Procedures

56-006-026-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Injector
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Last Modified: 17-Nov-2003