



Technical Service Bulletin

Technical Service Bulletin: tsb101398

Released Date: 05-Jun-2014

Revised Engine Speed Surges at Low or High Idle Symptom Tree.

Revised Engine Speed Surges at Low or High Idle Symptom Tree.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic corrects Base Engine Troubleshooting and Repair Procedure t066 Engine Speed Surges at Low or High Idle.

The eighth step reads: Engine position sensor (ESP) or circuit is malfunctioning. Check the engine position sensor.

Should read: Engine speed sensor (ESS) or circuit is malfunctioning. Check the engine speed sensor and circuit.

Reference Troubleshooting and Repair Manual, QSK45 and QSK60 Series Engines, Bulletin 3666261.

Document History

Date	Details
2014-6-3	Work Order 61241

Last Modified: 05-Jun-2014