



Technical Service Bulletin

Technical Service Bulletin: tsb101461

Released Date: 06-Aug-2004

Flywheel Tolerance Correction

Flywheel Tolerance Correction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is to inform the field of a correction to flywheel runout tolerances listed in Section 16 - Mounting Applications for the QSK45 and QSK60 engines.

Related Procedures

56-016-005-topic
(/qs3/pubsys2/xml/en/procedures/56/56-016-005-topic.html)

Flywheel
(/qs3/pubsys2/xml/en/procedures/56/56-016-005-topic.html)

Last Modified: 06-Aug-2004