



# Technical Service Bulletin

Technical Service Bulletin: tsb101759

Released Date: 19-Oct-2006

Revised Fan Idler Assembly

## Revised Fan Idler Assembly

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

**Note : This Service/Parts Topic 06T3-8A supersedes 06T3-8: replace 06T3-8 with this one.**

The purpose of this revised Service/Parts Topic is to announce that topic 06T3-8A incorporates the reference to the Service Manual, Bulletin Reference 4021530, which supersedes the Troubleshooting and Repair Manual, Bulletin Reference 3666261. Also to correct an error that was present on the version published on Quick Serve On Line.

This service topic details the procedures for removal/installation of the revised fan idler arrangement for the QSK45, QSK60 series engines.

The revised fan idler, slide arm type, went into production in August 2004 at the Daventry Engine plant. Engine serial number first was 33157417.

This service topic details the procedures for removal/installation of the revised fan idler arrangement for the QSK45 and QSK60 series engines.

### Related Procedures

56-008-029-tr  
(/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Fan Drive Idler Arm Assembly  
(/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Last Modified: 19-Oct-2006