



Technical Service Bulletin

Technical Service Bulletin: tsb101792

Released Date: 01-Mar-2018

Revision to Crosshead Procedure, Crosshead Pocket Inspection

Revision to Crosshead Procedure, Crosshead Pocket Inspection

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic changes the inspection criteria in valve crossheads for QSK45/60 diesel engines. The change adds reuse criteria for the valve stem pocket in the crosshead. Refer to Procedure 002-001 in Section 2 (</qs3/pubsys2/xml/en/procedures/56/56-002-001-tr.html>) of the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Document History

Date	Details
2018-2-27	Non-Product Problem Solving (PPS)

Last Modified: 01-Mar-2018